

PARK PLACE
GLENBROOK AT OXMOOR

HOUSING AUTHORITY
of the BIRMINGHAM DISTRICT

PROGRESS REPORT No. 91
January 2008



PARK PLACE - PHASE III

Exterior Plywood Installed w/ Partial Building Wrap Installed

PARK PLACE
GLENBROOK AT OXMOOR

HOUSING AUTHORITY
of the BIRMINGHAM DISTRICT

PROGRESS REPORT No. 91
January 2008



PARK PLACE - PHASE III
Interior Plumbing Distribution Panel

PARK PLACE
GLENBROOK AT OXMOOR

HOUSING AUTHORITY
of the BIRMINGHAM DISTRICT

PROGRESS REPORT No. 91
January 2008



PARK PLACE - PHASE III
Tub/Shower Fixture in Protective Wrapping, Prior to Installation

PARK PLACE
GLENBROOK AT OXMOOR

HOUSING AUTHORITY
of the BIRMINGHAM DISTRICT

PROGRESS REPORT No. 91
January 2008



PARK PLACE - PHASE III
Interior Partition Framing with Corner Balcony Beyond

PARK PLACE
GLENBROOK AT OXMOOR

HOUSING AUTHORITY
of the BIRMINGHAM DISTRICT

PROGRESS REPORT No. 91
January 2008



PARK PLACE - PHASE III
Framed Interior Corridor

PARK PLACE
GLENBROOK AT OXMOOR

HOUSING AUTHORITY
of the BIRMINGHAM DISTRICT

PROGRESS REPORT No. 91
January 2008



PARK PLACE - PHASE III
Upper Level Interior Partition Framing with Roof Truss Above

PARK PLACE
GLENBROOK AT OXMOOR

HOUSING AUTHORITY
of the BIRMINGHAM DISTRICT

PROGRESS REPORT No. 91
January 2008



PARK PLACE - PHASE III
Framing @ Interior Courtyard Area