

PARK PLACE
GLENBROOK AT OXMOOR

HOUSING AUTHORITY
of the BIRMINGHAM DISTRICT

PROGRESS REPORT No. 93
March 2008



PARK PLACE - PHASE III
Masonry Installations

PARK PLACE
GLENBROOK AT OXMOOR

HOUSING AUTHORITY
of the BIRMINGHAM DISTRICT

PROGRESS REPORT No. 93
March 2008



PARK PLACE - PHASE III
Kitchen/Living Area

PARK PLACE
GLENBROOK AT OXMOOR

HOUSING AUTHORITY
of the BIRMINGHAM DISTRICT

PROGRESS REPORT No. 93
March 2008



PARK PLACE - PHASE III
Stockpiled Gypsum Board on an Upper Level

PARK PLACE
GLENBROOK AT OXMOOR

HOUSING AUTHORITY
of the BIRMINGHAM DISTRICT

PROGRESS REPORT No. 93
March 2008



PARK PLACE - PHASE III
Framing at Lower Level for Mailboxes

PARK PLACE
GLENBROOK AT OXMOOR

**HOUSING AUTHORITY
of the BIRMINGHAM DISTRICT**

**PROGRESS REPORT No. 93
March 2008**



PARK PLACE - PHASE III
Corner Unit View w/ Balcony Beyond

PARK PLACE
GLENBROOK AT OXMOOR

HOUSING AUTHORITY
of the BIRMINGHAM DISTRICT

PROGRESS REPORT No. 93
March 2008



PARK PLACE - PHASE III
Living Area of Interior Unit w/ Courtyard Beyond

PARK PLACE
GLENBROOK AT OXMOOR

HOUSING AUTHORITY
of the BIRMINGHAM DISTRICT

PROGRESS REPORT No. 93
March 2008



PARK PLACE - PHASE III
Kitchen Plumbing Wall

PARK PLACE
GLENBROOK AT OXMOOR

**HOUSING AUTHORITY
of the BIRMINGHAM DISTRICT**

**PROGRESS REPORT No. 93
March 2008**



PARK PLACE - PHASE III